

AB Volvo Penta

Issued by	Date	Replaces	Insert	Page No.
42700 Global Warranty	2008-04-28	2008-01-15	7.3.102	1

RECALL CAMPAIGN
(4877-1674)

Carbureted gasoline engines .
Issued January 2008

PRODUCT: Carbureted gasoline engines, model 3.0GL, 4.3GL and 5.0GL.
Within serial number range 4012177265 - 4012204622

PROBLEM: Accelerated corrosion, resulting in fuel leak.

WHAT TO DO: Contact your Volvo Penta service dealer to schedule an appointment.

To find the nearest Volvo Penta dealer you may consult our *dealer locator* on our website

- **Please also see letter below**

AB Volvo Penta

Issued by	Date	Replaces	Insert	Page No.
42700 Global Warranty	2008-04-28	2008-01-15	7.3.102	2

January 2008

Re: Recall Campaign (4877-1674) – Volvo Penta carburetted gasoline marine engines

Dear Boat Owner:

This letter is intended to notify you of an important recall campaign involving your boat engine.

Volvo Penta purchases the carburetors from Holley Performance Products, Inc. Holley advises us that the alloy used to manufacture the carburettor castings did not meet its specifications thereby allowing accelerated corrosion. The corrosion process releases particles of oxidized metal that mix with fuel inside the carburettor blocking passages. Corrosion may also occur under sealing gaskets. Under these scenarios, a fuel leak may result and cause a fire if an ignition source is present. We are not aware any fire or explosion resulting from this defect to date.

Please contact your Volvo Penta servicing dealer to schedule an appointment for this important service. Your engine will be inspected to determine, by date code on the carburettor, whether a replacement carburettor is required. Inspection and carburettor replacement, if required, is estimated to take approximately 1.5 hours, and the service will be performed at no expense to you. **Do not use your boat until this important service is conducted.**

We apologize for this inconvenience.

Sincerely,

VOLVO PENTA