

VOLVO PENTA *Warranty Operational Procedure*

AB Volvo Penta

Issued by	Date	Replaces	Insert	Page No.
42100 Global Campaign Management	2010-03-29			

RECALL CAMPAIGN **(4877 – 1735)**

Carbureted Gasoline Sterndrive engines 3.0GL and 4.3GL

Model	Spec. Numbers	Serial Number Ranges 10 digit	7 digit
3.0GLP-J	3869388	4012250992 – 4012258677	A104193 – A112954
4.3GL-J	3869391	4012250707 - 4012258760	A103867 – A114420
4.3GL-JF	3869392	4012252403 – 4012258107	n/a

PROBLEM:

Volvo Penta discovered that the engine models above, within the serial number ranges listed, have carburetors which may have improperly fastened throttle plate retaining screws.

WHAT TO DO:

Contact your Volvo Penta service dealer to schedule an appointment.

To find the nearest Volvo Penta dealer you may consult our dealer locator on our website: www.volvopenta.com

VOLVO PENTA *Warranty Operational Procedure*

AB Volvo Penta

Issued by	Date	Replaces	Insert	Page No.
42100 Global Campaign Management	2010-03-29			

IMPORTANT RECALL NOTICE

OWNER NAME
ADDRESS

MODEL-ENGINE SERIAL NUMBER

Dear Volvo Penta Owner:

This notice is being sent to notify you of an important recall campaign involving carburetor on the Volvo Penta engine installed in your boat.

The Reason for this Campaign:

Volvo Penta has discovered that its carburetor supplier failed to properly secure the throttle plate mounting screws on the carburetor body in some engines. Through bench tests conducted after discovering this manufacturing defect, Volvo Penta learned that an unsecured throttle plate screw can fall into the engine causing damage to the engine and/or cause the throttle to stick in its last set position. The latter scenario could lead to loss of control.

What you need to do:

Do not use your boat until your carburetor can be inspected by an authorized Volvo Penta dealer. Please contact your authorized Volvo Penta dealer to schedule an appointment for this inspection and reference Volvo Penta Service Bulletin 23-1-23, for North America Service Bulletin 23-1-22. This campaign provides for the inspection and repair, if needed, of the carburetor at no charge. Due to service scheduling, your Volvo Penta dealer may require your boat for a period of time. **Do not use your boat until your carburetor can be inspected by an authorized Volvo Penta dealer.**

You may contact:

If you have any questions, please contact your Volvo Penta authorized dealer. (Dealers may be located at www.volvopenta.com.)

Your safety and continued satisfaction with your Volvo Penta powered boat is extremely important to us. We apologize for any inconvenience this may cause and appreciate your cooperation in having this important recall completed as quickly as possible.

Sincerely,

Volvo Penta Product Support